



Minut Point Teardown

Let's take apart a defective point and see what's on the inside

Written By: Kraven Craft



Step 1 — Removing batteries and first screws



- Turn your point upside down and you'll see a battery cover and three (3) screws.
- Begin by taking out the 4 AA batteries by removing the cover.
- Once the batteries are removed you can remove the 3 PH1 screws.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-17 03:43:24 AM.